

PGMV2 TP1010C Upgrade programmer user's Guide

1. Install the PL2303 USB driver file into your windows operating PC(down load from <http://www.thunderpowerrrc.com>)
2. Connect the TP1010C Charger input power wire to 12V Power supply with 10 Ohm resistor or use 9V FC-1 battery.(See Fig-2)
3. Connect 6pin connector into TP1010C charger and the USB cable to the PC.
4. Open PGMV2 TP1010CVxx.exe(down load the latest program from <http://www.thunderpowerrrc.com>)
5. Click on “Upgrade”




Fig-1 PGMV2 TP1010CVxx.exe windows

- Important Note: The input wire must be used shown Fig-2.




Fig-2 Input wire connection example